



External painting and window repairs

Rendall and Rittner Management, Lancaster Close, Westminster, London

Highlights

Axis undertook external repairs and redecorations to a multi occupied property, located in the City of Westminster's cosmopolitan area of Bayswater.

Work was undertaken to the front elevation of the occupied flats to include new rainwater and drainage systems. A design scaffold system was set up with security cameras and alarms, to enable a non restrictive access to all elevations for Axis workers whilst offering a secure environment to the building, during out of hours working.

All windows were individually inspected and serviced prior to re-decoration and were repainted together with any joinery and metal window repairs, to include; a repair care system, followed by installation of new glazing. Work led dormer roofs and cheeks were removed and replaced, together with lead work and timber work carried out on the roof with the removal & replacement of defective sections of the lead flashing. Minor masonry and brick work repairs were also carried out. A full refurbishment of the marble wall panel and entranceway was undertaken, offering a fresh & clean main entrance for the residents.

Specifications

- Window repair
- External painting
- Marble wall/ entrance way refurbishment
- Leadwork
- Masonry repairs
- Brickwork
- Joinery repairs

6 months duration

Contact

marie.partner@axiseurope.com

0203 597 2538

axiseurope.com